

GAWLER RIVER FLOODPLAIN MANAGEMENT AUTHORITY

PO Box 366 Seacliff Park, SA 5049

P: 0407 717 368

E: eo@grfma.com

W: www.gawler.sa.gov.au/grfma

Dear Member,

NOTICE OF MEETING

Notice is hereby given pursuant to Clause 6 of the Charter that a meeting for the GRFMA Audit and Risk Committee has been called for:

DATE: Tuesday 25 November 2025

TIME: 11:30am

PLACE: Online Meeting – MS Teams




David E Hitchcock

EXECUTIVE OFFICER



The Barossa Council

Gawler



AGENDA

GAWLER RIVER FLOODPLAIN MANAGEMENT AUTHORITY AUDIT AND RISK COMMITTEE MEETING

**Tuesday 25 November 2025
Online Meeting – MS Teams**

- 1. Present**
- 2. Apologies**
- 3. Minutes of the Previous Meeting.....Page 3**

Confirmation of the Minutes of the previous GRFMA Audit and Risk Committee meeting held on 8/10/2025.
- 4. Business Arising from the Minutes**
 - 4.1 Actions on Previous Resolutions.....Page 7**
- 5. General Business**
 - 5.1 Intermediate Surveillance Inspection of Bruce Eastick.....Page 8**
North Para Flood Mitigation Dam
 - 5.2 GRFMA Insurances – LGAAMF.....Page 13**
 - 5.3 Progress Report GRFMA Strategic and Annual.....Page 15**
Business Plan 2025-2026
- 6. Confidential Items**

Nil
- 7. Next Meeting**

February 2026
- 8. Closure**

Agenda Item: **3**
Committee: **GRFMA Audit and Risk Committee**
Meeting Date: **25 November 2025**
Title: **Minutes of the Previous Meeting**

Recommendation:

That the minutes of the GRFMA Audit and Risk Committee meeting held on 8 October 2025, as per copies supplied to members, be adopted as a true and correct record of that meeting.

The minutes were circulated to members and are attached to this report.

MINUTES

GAWLER RIVER FLOODPLAIN MANAGEMENT AUTHORITY AUDIT AND RISK COMMITTEE MEETING

Wednesday 8 October 2025

11:30am
MS Teams

1. Present

- Mr Peter Brass, Independent Member, Chairman
- Cr Malcolm Herrmann, Adelaide Hills Council
- Mr Greg Pattinson, City of Playford
- Mr David Hitchcock, Executive Officer

2. Apologies

Nil

3. Minutes of the Previous Meeting

GAC25/013 Minutes of the Previous Meeting

Moved: Cr M Herrmann

Seconded: Mr G Pattinson

That the minutes of the previous GRFMA Audit and Risk Committee meeting held on Tuesday 12 August 2025, as per copies supplied to members, be adopted as a true and correct record of the meeting.

CARRIED UNANIMOUSLY

4. Business arising from the Minutes

4.1 Actions on Previous Resolutions

Noted

5. General Business

5.1 GRFMA 2024/2025 Financial Statements and Audit Report

GAC25/14 GRFMA 2024/2025 Financial Statements and Audit Report

Moved: Mr G Pattinson

Seconded: Cr M Herrmann

That the GRFMA Audit and Risk Committee:
1. Notes GRFMA 2025/2026 Budget Review 1.

2. *Requests the Executive Officer provides the documents to the next GRFMA Board meeting (16 October 2025) for adoption as the current budget for the period ended 30 June 2026.*

CARRIED UNANIMOUSLY

Members noted:

- Balance Sheet, Current Liabilities – Borrowings had moved from \$286,186 (adopted Budget) to \$32,404 (BR1) and requested the Executive Officer to provide notation to clarify why this has changed.

5.2 GRFMA Insurances

GAC25/15 GRFMA Insurances

Moved: Mr G Pattinson

Seconded: Cr M Herrmann

That the GRFMA Audit and Risk Committee:

1. *Requests the Executive Officer to seek further information to clarify the aspects and process of:*
 - a) *Applying for membership to the LGA Mutual Asset Fund (LGAAMF); and*
 - b) *The process involved in facilitating insurance of the Dam as an asset.*
2. *Notes that the process of committee meeting considerations reflects committee advice rather than individual recommendations.*
3. *Request the Executive Officer to advise Constituent Councils and participating State Government agencies, to check if their Professional Indemnity cover extends to other authority committees such as the GRFMA Technical Advisory Panel.*

CARRIED UNANIMOUSLY

The meeting considerations were recorded as.

- Does applying for insurance coverage for the Dam also serve as an application for LGAAMF membership? Should it be a separate process, can application be made at the same time?
- An independent Dam condition assessment is to be provided to the GRFMA Board on 16 October 2025. This report will provide a basis for insurance cover considerations by GRFMA and LGAAMF.
- Dam damage insurance is treated as a distinct asset separate from public liability coverage in dam management.
- Noted that GRFMA Technical Assessment Panel is indemnified for civil liabilities – to the extent that individuals who sit on that committee are members of the GRFMA Board then yes. If they are not, then it would be prudent to check if they come with their own Professional Indemnity cover.

5.3 Balance Date Audit Management Letter: Financial Year Ended

GAC25/16 Balance Date Audit Management Letter: Financial Year Ended

Moved: Cr M Herrmann

Seconded: Mr G Pattinson

That the GRFMA Audit and Risk Committee.

1. *Receives the 2024/2025 External Audit Report and financial results report (regulation 10).*

2. *Recommends that the reports be submitted to the 16 October 2025 GRFMA meeting for adoption.*

CARRIED UNANIMOUSLY

The meeting requested the Executive officer to further clarify intent of commentary in the Financial Results report (regulation 10), at Statement of Comprehensive Income - Materials, Contracts and Other Expenses- *\$270K of the Business Case consultancies was not spent in 25/26. On the basis was the \$270K not spent in 2024/25 or is to be spent in 2025/26.*

6. Confidential Items

Nil

7. Other Business

The meeting requested the Executive Officer to make inquiries with Dean Newbery to facilitate availability of the 2025/2026 GRFMA External Audit Plan at the February 2026 Audit and Risk committee meeting.

8. Next Meeting

Early December 2025

9. Schedule of Meetings

August 2025	Annual Financial Statements – Audit report; 2024/2025 – Auditor to attend.	Completed
October 2025	Budget Review 1 variations consideration.	Completed
December 2025	Budget Review 2 variations consideration. Operation of the Regional Subsidiary – Business Plan progress	
February 2026	Budget Review 3 variations consideration. External Audit Plan	

10. Closure

The Chairman thanked the members for their attendance and contribution.
The meeting closed at 12:26pm.

Chair _____ Date _____

Agenda Item: 4.1
Committee: GRFMA Audit and Risk Committee
Meeting Date: 25 November 2025
Title: Actions on Previous Resolutions

Number	Resolution	Action
GAC25/14	<i>That the GRFMA Audit and Risk Committee:</i> <i>Notes GRFMA 2025/2026 Budget Review 1.</i> <i>Requests the Executive Officer provides the documents to the next GRFMA Board meeting (16 October 2025) for adoption as the current budget for the period ended 30 June 2026.</i>	Completed
GAC25/15	<i>That the GRFMA Audit and Risk Committee:</i> <i>Requests the Executive Officer to seek further information to clarify the aspects and process of:</i> <i>Applying for membership to the LGA Mutual Asset Fund (LGAAMF); and</i> <i>The process involved in facilitating insurance of the Dam as an asset.</i> <i>Notes that the process of committee meeting considerations reflects committee advice rather than individual recommendations.</i> <i>Request the Executive Officer to advise Constituent Councils and participating State Government agencies, to check if their Professional Indemnity cover extends to other authority committees such as the GRFMA Technical Advisory Panel.</i>	Refer Item 5.2 City Playford, Barossa and DEW advised (current members)
Notes	The meeting requested the Executive Officer to make inquiries with Dean Newbery to facilitate availability of the 2025/2026 GRFMA External Audit Plan at the February 2026 Audit and Risk committee meeting.	Inquiries have been made. Response pending

Agenda Item:	5.1
Committee:	GRFMA Audit and Risk Committee
Meeting Date:	25 November 2025
Title:	Intermediate Surveillance Inspection of Bruce Eastick North Para Flood Mitigation Dam

Recommendation:**That the GRFMA Audit and Risk Committee:**

- 1. Receives a presentation from GHD on the Intermediate Surveillance Inspection of Bruce Eastick North Para Flood Mitigation Dam, report.**
 - 2. Recommends that the report be provided to the 4 December 2025 GRFMA Board meeting for consideration and attention to recommendations.**
 - 3. Requests that an update on the GRFMA Board deliberations be provided at the next Audit and Risk Committee meeting.**
-

GHD Pty Ltd (GHD) has been engaged by Gawler River Floodplain Management Authority (GRFMA) to undertake the 2025 Intermediate Surveillance Inspection of Bruce Eastick North Para Flood Mitigation Dam.

This Intermediate inspection has now been undertaken in accordance with the Australian National Committee On Large Dams (ANCOLD, 2003) guidelines and represents compliance (in part) with the due diligence obligations of a dam owner in managing the dam to current guidelines, in lieu of any dam safety regulatory authority (or similar) in South Australia.

The inspection report has relevance to item 5.2 Insurances, as it provides important considerations for assessment of appropriate insurance coverage for the Bruce Eastick North Para Flood Mitigation Dam.

Mr Tom Gersekowski, Senior Engineer – Dams at GHD, will present (via meeting link) and explain the report and recommendations at the 25 November 2025 meeting.

The Intermediate Surveillance Inspection report will also be provided to the 4 December 2025 GRFMA meeting.

Extract of information from the report

The dam and its major appurtenant structures/components were visually inspected by GHD on 3 October 2025, jointly with David Hitchcock as the GRFMA representative. The inspection included:

- Visual inspection of the dam crest, upstream face, the downstream face and abutments.
- Visual inspection of the HLOP (from base of dam only), LLOP and secondary spillway. Visual inspection of the stilling basin and weir (noting that the stilling basin was partly submerged at the time of the inspection).

The instrumentation monitoring program and dam safety inspection program has been reviewed. An assessment of the appropriateness and adequacy, the effectiveness, and the application of the dam safety management has been undertaken.

The following comments and conclusions have been made based on the inspection and review of the dam safety documentation:

The visual inspection identified the following key outcomes:

- Minor cracking was observed on the dam. This is likely attributed to thermal shrinkage and does not pose an immediate risk to dam safety.
- Both the left and right abutments of the dam were found to be in generally satisfactory condition. Note that vegetation on the abutments should be removed.
- The secondary spillway crest was in fair condition, with minor cracking and grass growth at the parapet wall connection that should be monitored for spalling.

The dam safety documentation was also reviewed, noting:

- The stilling basin was submerged at the time of the inspection. Exposed areas of the stilling basin appeared in satisfactory condition.
- Both HLOPs were generally in satisfactory condition. Minor cracking and spalling were also noted around the downstream edges of the right HLOP, along with wasp nests that pose a safety risk for maintenance but not a structural concern.
- It was recommended to develop a document that encompasses the Dam Safety Management Program.
- Several updates to the OMM were recommended; notwithstanding, the current OMM generally satisfies the recommended contents by ANCOLD (2003).

It was recommended to update the Dam Safety Emergency Plan, in consideration of recent updates to the Australian Warning System, to provide more tangible triggers for escalation of a dam emergency during the event and improve the instructions for communications protocols. Such changes aim to improve usability during a dam emergency.

A review of the performance of the dam, based on the current safety review for the Dam, identified:

- There is uncertainty in the actual flood handling capacity of the dam. It should be reviewed using the recently updated inflows from the hydrology assessment (HARC 20205), but also with a comprehensive review of the spillway rating curve.
- The dam break and consequence category assessment should be updated using the latest hydrology data.
- The stability of the dam should be reviewed using the latest flood loading data and include an updated seismic hazard assessment.
- Concrete coring of the dam has been recommended to confirm the design assumptions and material parameters.

Based on the review of the respective input studies, the dam may not satisfy a standards-based assessment of engineering performance against the respective ANCOLD guidelines.

In consideration of these aspects, it is recommended to undertake a Safety Review of the dam to evaluate the safety of the dam. The Safety Review may also investigate a risk-based assessment of the dam, which is an accepted method of evaluating the safety of a dam that does not satisfy the standard-based approach.

The following recommendations for the North Para Dam have been made by GHD on the basis of visual observations made during the Intermediate inspection, and the assessment of the performance and dam safety management documentation provided to GHD by GRFMA.

The recommendations have been separated with respect to the priority and classification of the resulting actions as summarised below.

- P1: Immediate action Critical actions that need to be undertaken immediately to safeguard the integrity of the dam or the safety of personnel.
- P2: Short-term action Operation, maintenance, minor works, investigation or monitoring issues required detailed attention or action within the next 12-24 months, in addition to normal routine actions and monitoring.
- P3: Long-term action Lower priority, long-term operation, maintenance, minor works, investigation or monitoring issues that will require attention within 24-48 months.
- P4: Major works Items requiring capital works upgrades to address dam safety and/or business risks.

9.2 Recommendations

The following recommendations for the North Para Dam have been made by GHD on the basis of visual observations made during the Intermediate inspection, and the assessment of the performance and dam safety management documentation provided to GHD by GRFMA. The recommendations are provided as Table 9.1. The recommendations have been separated with respect to the priority and classification of the resulting actions as summarised below.

- P1: Immediate action** Critical actions that need to be undertaken immediately to safeguard the integrity of the dam or the safety of personnel.
- P2: Short-term action** Operation, maintenance, minor works, investigation or monitoring issues required detailed attention or action within the next 12-24 months, in addition to normal routine actions and monitoring.
- P3: Long-term action** Lower priority, long-term operation, maintenance, minor works, investigation or monitoring issues that will require attention within 24-48 months.
- P4: Major works** Items requiring capital works upgrades to address dam safety and/or business risks.

Table 9.1 2025 Intermediate Surveillance Report recommendations

Recommendation from the 2025 Inspection	Priority
R 2025(4.3.2)(a) Remove vegetation and saplings from the left abutment block.	P2
R 2025(4.3.2)(b) Repair handrails footings at the left abutment.	P1
R 2025(4.3.2)(a) Remove vegetation and saplings from the right abutment overflow channel.	P2
R 2025(4.3.3)(a) Remove obstruction from the weir outlet.	P2
R 2025(4.3.3)(b) Remove any saplings > 300 mm in height from the rock at the left side of the stilling basin.	P2
R 2025(4.3.3)(c) Remove the deceased animal from the outlet weir of the stilling basin.	P2
R 2025 (4.3.4)(a) Remove grass/vegetation from within 5 m of the secondary spillway, including any vegetation on the spillway.	P2
R 2025 (4.3.5) Repair concrete around the right HLOP outlet to prevent future concrete spalling.	P2
R 2025(5)(a) Develop an instrumentation layout plan for the dam and include this in the OMM.	P2
R 2025 (5)(b) Collect all available reservoir level and rainfall data to a single consolidated source.	P2
R 2025(5)(c) Collate all available survey data to a consolidated source to plot the movement of the dam with time.	P2
R 2025(5)(d) Confirm when the latest survey control survey was completed and document this in the dam log book.	P2
R 2025(6.2)(a) Develop a DSMP for North Para Dam.	P2
R 2025 (6.3)(a) Undertake a comprehensive update the to the DSEP in consideration of the recommendations made in the 2025 Intermediate Surveillance Report of North Para Dam.	P2
R 2025 (6.4)(a) Undertake a comprehensive update the to the OMM in consideration of the recommendations made in the 2025 Intermediate Surveillance Report of North Para Dam.	P2
R 2025(7.2)(a) Undertake a review of the flood handling capacity of the dam.	P3
R 2025 (7.3)(a) Update the dam break consequence category with the incorporation of the revised hydrology data per ARR 2019 v 4.2.	P3
R 2025 (7.3)(b) Confirm the appropriateness of the assumption of 'adequate warning time' is provided for downstream PAR.	P3
R 2025 (7.3)(c) Update inundation maps to show depth (m), level (m AHD), depth-velocity product, and the impacted PAR.	P3

Recomendation from the 2025 inspection	Priority
R 2025 (7.4)(a) Undertake an updated stability assessment aligned with the guidance of ANCOLD (2013) to review the performance of the dam, including updated flood and seismic loading conditions.	P3
R 2025 (7.5)(a) Undertake concrete coring to verify the material design assumptions for the dam.	P3
R 2025(7.6)(a) Complete a Safety Review for North Para Dam per ANCOLD (2003).	P3
Previous recommendations carried forward	
R 2018(6) The cracks in the second spillway should be visually monitored at each inspection for significant change.	P2 (ongoing)
R 2025 Patch the porous concrete surfaces and chipped corners of the inlet chamber walls.	P2

Agenda Item:	5.2
Committee:	GRFMA Audit and Risk Committee
Meeting Date:	25 November 2025
Title:	GRFMA Insurances – LGAAMF

Recommendation:

That the GRFMA Audit and Risk Committee recommends that the GRFMA Board make a submission to the LGA Asset Mutual Fund (LGAAMF) to consider appropriate insurance coverage for the Bruce Eastick North Para Flood Mitigation Dam.

The GRFMA Audit and Risk Committee has been liaising with the Local Government Association Mutual Liability Scheme to address issues pertaining to appropriate insurance coverage for the Bruce Eastick North Para Flood Mitigation Dam.

Most recently the 8 October 2025 committee meeting resolved:

That the GRFMA Audit and Risk Committee:

1. *Requests the Executive Officer to seek further information to clarify the aspects and process of:*
 - a) *Applying for membership to the LGA Mutual Asset Fund (LGAAMF); and*
 - b) *The process involved in facilitating insurance of the Dam as an asset.*
2. *Notes that the process of committee meeting considerations reflects committee advice rather than individual recommendations.*
3. *Request the Executive Officer to advise Constituent Councils and participating State Government agencies, to check if their Professional Indemnity cover extends to other authority committees such as the GRFMA Technical Advisory Panel.*

The meeting considerations were recorded as:

- Does applying for insurance coverage for the Dam also serve as an application for LGAAMF membership? Should it be a separate process, can an application be made at the same time?
- An independent Dam condition assessment is to be provided to the GRFMA Board on 16 October 2025. This report will provide a basis for insurance cover considerations by GRFMA and LGAAMF.
- Dam damage insurance is treated as a distinct asset separate from public liability coverage in dam management.
- Noted that GRFMA Technical Assessment Panel is indemnified for civil liabilities – to the extent that individuals who sit on that committee are members of the GRFMA Board, then yes. If they are not, then it would be prudent to check if they come with their own Professional Indemnity cover.

Response - LGA Asset Mutual Fund (LGAAMF)

“As the Gawler River Floodplain Management Authority (GRFMA) was formed as a Regional subsidiary under Section 43, Schedule 2 of the Local Government Act 1999, they are an Eligible Body for membership to the LGA Asset Mutual Fund in accordance with Scheme Rule 2.5.5.

As the GRFMA only have one asset they are considering protection for, being the Bruce Eastick Dam structure, the LGA Asset Mutual Fund will require additional information to consider the risk prior to providing an offer of membership, noting the nature of the engineered structure and the purpose for which it was constructed which should be engineered to withstand flood related events.

It is recommended that GRFMA provide the following for the LGAAMF to consider the risk further:

- 1. A current Dam condition report*
- 2. Details/confirmation of what flood events the Dam was constructed to withstand*
- 3. A valuation of the Dam confirming its current replacement cost, if it was required to be rebuilt following a loss in its current form. i.e like for like, not betterment.*
- 4. Any details of significant weather events where the dam has breached or nearly breached.*
- 5. Any previous loss and or damage sustained to the dam structure that required repair or replacement.*

Following receipt of the above, the LGAAMF can consider the risk further and then clarify the extent of protection it can or cannot provide.

After reviewing the information and committee input, the Fund will inform GRFMA whether membership is offered, based on risk, and outline any related conditions or requirements."

GRFMA Audit and Risk Committee considerations

The Intermediate Surveillance Inspection report for the Bruce Eastick North Para Flood Mitigation Dam (item 5.1) covers items 1, 2, 4, and 5 from the LGAAMF information requirements.

An independent valuation dated July 1, 2023 (item 3), is available separately and can be provided to LGAAMF.

Despite the recommendations in the surveillance report, it is believed that sufficient information exists to support GRFMA's submission to LGAAMF, allowing them "to consider the risk further and then clarify the extent of protection it can or cannot provide".

This will help GRFMA determine whether insurance coverage for the Bruce Eastick North Para Flood Mitigation Dam is feasible.

Agenda Item:	5.3
Committee:	GRFMA Audit and Risk Committee
Meeting Date:	25 November 2025
Title:	Progress Report GRFMA Strategic and Annual Business Plan 2025-2026

Recommendation:

That the GRFMA Audit and Risk Committee receives and notes the GRFMA Strategic Plan and Business Plan 2025/2026 progress report.

On 28/06/2023 the GRFMA engaged LUVROK Pty Ltd to undertake GRFMA Executive Officer services, in accordance with the agreed contract for service, for the term 1 July 2023 to 31 December 2025.

Mr David Hitchcock is identified as the key person providing the services pursuant to the agreed terms.

A work management program has been established to identify and measure actions and progress of the GRFMA Strategic Plan and Business Plan 2025/2026.

See attached copy "GRFMA work requirements November 2025" for further details.

GRFMA work requirements

EO Service requirements

Powered by  monday.com

Name		Date	Date 1
Maintain the business office of the Authority	Done	2025-11-17	
Prepare Agendas & Minutes Attend meetings	Done	2025-11-17	
Attend the minute actions as required	In progress	2025-11-17	
Management of the GRFMA strategic management documents	In progress	2025-11-17	
Subitems	Status	Date	
Asset Management Plan	In Progress	2025-11-17	
Strategic Plan	Done	2025-11-17	
Long Term Financial Plan	Done	2025-11-17	
Prepare the Annual Report.	Done	2025-11-17	
Prepare the Annual Business Plan, Budgets and reports	Done	2025-06-30	2026-06-30
liaise with constituent councils, Green Adelaide, Northern Yorke Landscape Board, Stormwater Management Authority	Done	2025-11-17	
Engage with relevant federal and state ministers/MPs & CEOs	In progress	2025-11-17	
Actively pursue grant funding	Done	2025-11-17	
Proactively promote the works and activities of the Authority.	In progress		
Report annually on progress with implementation of the SMP .	To be scheduled	2026-02-02	
Develop and implement a schedule of flood mitigation infrastructure works for the SMP	In progress	2025-12-16	
		2025-06-30 to 2026-02-02	2026-06-30

Meeting agenda process

Name	Status	Date	Date 1
Draft Agenda reports	Done	2025-11-17	
Forward drafts to Admin to format and compile	Done	2025-11-17	
Send Agenda to Board, Councils Town of Gawler webpage	Done	2025-11-17	
Draft minutes , KOS send to Admin to format	In progress	2025-11-27	
Send minutes and KS to Board, Councils, Town of Gawler webpage	In progress	2025-11-27	
Action minute resolutions and directions	In progress	2025-11-27	
		2025-10-06 to 2025-10-21	

Strategic Plan Priority Actions

Name	Status	Date	Date 1
Work to facilitate delivery of the objectives of the Gawler River Stormwater Management Plan	Done	2025-11-04	
Review, with Constituent Councils and stakeholders, design standards for infrastructure works including costs and benefits	In progress	2025-11-04	2026-07-01
In conjunction with the Constituent Councils, develop and implement a schedule of flood mitigation infrastructure works for the Gawler River referencing the Gawler River Stormwater Management Plan	To be scheduled	2025-11-04	2026-07-01
Working with the Constituent Councils, develop a framework to clearly articulate the respective roles and responsibilities of the Authority and the Councils and suitable partnering arrangements to maintain a low-cost base for the Authority.	Done	2025-11-04	2026-07-01
Continue to advocate for improved governance and funding arrangements for flood avoidance, resilience, and mitigation in South Australia	Done	2025-11-04	2026-07-01
Assist the Constituent Councils in communicating with general communities and specific interest groups in relation to flood mitigation for the Gawler River	In progress	2025-11-04	2026-07-01
		2025-11-04	2026-07-01

GRFMA Projects

Name	Status	Date	Date 1
Deliver Stormwater Management Plan	Done	2025-11-04	
Engage with DEW with Business Case completion	Done	2025-11-04	2026-12-14
Market Test and appointment GRFMA Chairperson position	Done	2024-05-01	
Transition EO services to corporate status	Done	2023-06-30	
Deliver quarterly GFMA Audit Committee meetings	Done	2025-10-08	2025-12-16
Prepare and finalise 25/26 Financial Statements	To be scheduled		
		2023-06-30 to 2026-07-21	2025-12-16 to 2026-12-14

Maintenance and Operations			
Name	Status	Date	Date 1
Delivery of scheduled maintenance at Dam as per Maintenance Cost Analysis 2023-2032.	In Progress	2025-11-04	
Scheduled inspections and environmental management of land associated with the Dam location	Done	2025-11-04	2025-12-16
Revaluation of the Bruce Eastick North Para Flood Mitigation Dam (5 year program	Done	2024-02-01	
Continuation of the revegetation program	Done	2025-11-04	
Implementation of an Information Management Framework for a digital environment	Done	2024-06-26	
		2024-02-01 to 2025-11-04	2025-12-16